

FIG. 1







Tis: POWER CONVERTER OPERATION START TEMPERATURE Ti α : FORCIBLE COOLING START TEMPERATURE RISE AMOUNT Ti β : FORCIBLE COOLING STOP TEMPERATURE RISE AMOUNT

FIG. 4

Tis [C]	Tiα [°C]	Tiβ [°C]
-20	70	47
-10	65	44
0	60	41
+10	55	38
+20	50	35
+30	45	32
+40	40	29








FIG. 6

